


Item	Part#	Description	Qty.
1	PR-2000-01	Stand Bottom Frame	1
2	PR-2000-22	U-Arm Holder	3
3	PR-2000-WHE	Rear Wheel	2
4	PR-2000-13	Rear Wheel Axle Plate	2
5	PR-2000-31	Rear Wheel Axle	1
6	P10-05A	3.5" Front Caster	2
7	P10-35	2x4" End Cap	2
Α	S-170	M8-16 PPHS Zink	16
В	S-62	M6-10 Phil. PH Screw	6
С	W-18	5/8" Washer	8
D	W-19	5/16" Lock Washer	16
Е	SR-03	5/8" External Snap Ring	2
F	P-05	1/4-10 U-Bolt	2
G	N-06	1/4-20 Nut	4
Н	W-20	1/4 Lock Washer	4





tem	Part#	Description	Qty.
_	PR-2000-06	Chassis	1
2	PR-2000-04	Stand Rear Member	-
3	PR-2000-02	Stand Left / Right Member	2
4	P6-18	Cable Holder	2
2	M-124	Euro Receptacle	1
9	PR-2000-Y2	Decal - Pro Spot (18")	2
Α	S-170	M8-16 Large Head Screw	20
α		M3_12 Scrow	۷



	Part#	Description	Qty.
PF	४-2000-08	PR-2000-08 Chassis Back Panel	1
ᆸ	PR-2000-15	Boom Bracket	1
	P10-38	Zink Hook	-
Ф	PR-2000-12	Fan Guard	2
	F-39	Air Fitting 1/4NPT - 1/4 line	-
	P10-12	Strain Relief	1
Р	PR-2000-45	ID Label	-
		Circuit Breaker - Rear Panel	1
		Cooling Fan	2
	S-62	M6-10 Screw	4
		8-32x3/4"L Flat Head Screw	8
		8-32x2 1/2"L Screw	2
	WL-13	6/4 Power Cable	30
	S-44	M6-16 PHMS	2
	V-07	8-32 Nut	1
l.	11/1/1/1		,









Qty.


1

5


4










Item	Part#	Description	Qty.
1	PG-16	Handle Mounting Block	1
2	PG-15	Brass Electrode Holder	1
3	PG-14	Cast Handle	1
4	F-44	Switch	1
5	F-46	1/2" Nylon Plug	2
6	PR-2000-43		1
7	PR-2000-WC3	Weld Cable 350 mcm 7'L (84")	1
8	H-14	5/32 Black Poly Hose - 1'	2
Α	S-86	M4-8 SHCS Zink	6
В	S-88	M6-20 SHCS Zink	3
С	S-138	M10-20 SHCS Zink	1
D	N-03	M6 Nut	2
Е	W-65	M10 Lock Washer	1






- 1. Insert bolts (A) and secure it with nuts (B) as shown on Fig. 1
- 2. Attach MIG bottle holder (C) using 2 provided screws (D) for the top holes and 2 existing screws (E) for the bottom holes as shown on Fig. 2
- 3. Tighten all bolts firmly.
- 4. Attach two eye bolts as shown in Fig 3. and attach chain (F)
- 5. Insert MIG welder and place it on top of the bolts you attached in Step 1 secure the MIG welder with aprovided washer (K) and nut (B).
- 6. Connect electrical plug to two holes on rear member.








Please NOTE: Side Member on this drawing has been removed for viewing purposes only! **Do not** remove side member on your welder during installation.

Item	Part#	Description Qty.
1	PR-2000-16	Boom 1
2	PR-2000-19	Boom Extension 1
3	PR-2000-20 PS-005	Boom Slide 1
7	C-09	Cable Saddle 1 Snap Hook w/latch 2" 1
A	S-95	M8 x 50 SHCS Zink 2
В	N-38	M8 Nut
	PR-2000-49	Boom Cable Assembly (includes items below)
8	C-01	3/16 Wire Rope 1' length 3.5
5	C-02	10/10 Compression Nut
6	C-03	



Qty.

Description

Housing

Acting Shaft

Piston

upport Cover

tear Cover

annel Cover

	Cylinder I	Cylinder I	Double A	Static Pis	Dynamic	Bushing	Bushing (Upper Re	Cable Sup	Electrode	Wire Cha	Cast Han	Spring																	(
Part#	PG-01	PG-02	PG-03	PG-05	PG-06	PG-08	PG-09	PG-10	PG-11	PG-12	PG-13	PG-14	PG-18										Ø					•		
Item	1	2	3	4	5	9	7	8	6	10	11	12	13																	
																				6	9	/	/	\\\ /						
																						3	, Э	/	/	ę		/	/ * \	
																											Ę)		
Qty.	2	τ-	_	~	_	τ-	4	2	~	က	~	9	2	~	4	τ-	_	τ-	_	1	2	τ-	1.5	4	2	2	9	9	1	_
			_									et Cap	rew														ctor			
Description		unvented	6mm reducer			g 4mm				nt set screw	t HH bolt	M4 x 10 Button Head Socket Cap	s flat head screw	nt set screw	nt set screw	p ring	_	ər	er	her		ut	y Hose - 1"	y Hose - 1"			ocket Connector	n Connector	lousing	guisr
ă	Switch	Plug 1/2 nylon un	90deg. 4mm - 6m	90deg. 6mm	90deg. 4mm	90deg. In-fitting 4	M4 x 8 SHCS	M6 x 20 SHCS	M8 x 20 SHCS	M6 x 8 cup point	3/8 × 16 × 1-1/4	t x 10 Buttor	M4 x 30 phillips f	M4 x 8 cup point	M4 x 6 cup point	" external snap	3/8" flat washer	3/8" lock washer	5/16" flat washer	5/16" lock washer	M6 nut	3/8 x 16" hex nut	4mm Black Poly	6mm Black Poly	#214 O-Ring	#232 O-Ring	24-18 AWG Sock	24-18 AWG Pin (3-pin Female Housing	3-pin Male Housing
Part#	F-44 Sw	F-46 Plu		F-54 900	F55 900		S-86 M4				S-178 3/8	S-179 M4	S-180 M4	S-181 M4	S-182 M4	SR-09 1"	W-05 3/8	W-14 3/8	W-16 5/1	W-19 5/1	N-03 M6	8/E 80-N	H-14 4m	H-15 6m	M-170 #2	M-171 #2:	T-19 24-	T-21 24-	T-52 3-p	T-55 3-p
		_				_		S	S	ώ	Ġ	Ġ	Ġ	Ġ	Ġ	S				×	Z	Z		_	Ž	Ž				-
Item	A	В	S	Ω	Ш	Щ	ග	エ		7	ᅩ	_	Σ	Z	0	Д	Ø	Υ.	S	⊥	N	>	\otimes	×	>	Z	AB	AC	AD	AE

